



# Assembly Instruction



Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other.

# Assembly Instruction



# Assembly Instruction

## Hardware arts




M8\*25

**A** 12PCS



M8\*35

**B** 4PCS+1PC




M8\*45

**C** 3PCS




**D** 2PCS



**E** 1PC


## Part list




**1** 1PC



**2** 2PCS




**3** 1PC




**4** 2PCS




**5** 2PCS




**6** 2PCS




**7** 1PC



**8** 1PC



**9** 2PCS



**10** 1PC



**11** 1PC




**12** 4PCS




**13** 2PCS

# Assembly Instruction


Step:1




Step:2



Step:3




Step:4




# Assembly Instruction


Step:5




Step:6



Step:7




Step:8




# Assembly Instruction


Step:9



Step:10



Step:11



Step:12

