









ASSEMBLY INSTRUCTION




PARTS LIST


					
A	B	C	D	E	F
X1	X1	X1	X1	X1	X1
					
G					
X2					

HARDWARE LIST


	
1	X6




Step1




Step2




Step3




Step4





Step5




Step6








Step7



ASSEMBLY INSTRUCTION





PARTS LIST

					
A	B	C	D	E	
X1	X1	X1	X1	X1	


HARDWARE LIST

	
1	X4


Step 1




Step2





Step3




Step4










Step5




ASSEMBLY INSTRUCTION




PARTS LIST


					
A X1	B X1	C X1	D X1	E X1	F X1
					
G X2					

HARDWARE LIST


	
1 X6	




Step1




Step2




Step3




Step4





Step5




Step6




Step7




ASSEMBLY INSTRUCTION



PARTS LIST



X1



B

X1


A

HARDWARE LIST




X4

1



Step 1



Step2

