




Przednia część płyty - brak okleiny PCV.
The front part of the board - lack veneer PCV.



10			
9	28	42	1
8			
7	D	E	F
6	130-150	6	6
5	4.0x13mm		
4	H	J	K
3	86	4	2
2			
1	L	M	N
0	8	12	8
	P	R	S
	2	6	2
	4,2x13		
	T	U	
	12	6	

Przednia część płyty - okleina PCV.
The front part of the board - veneer PCV.



0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 zmierz przekątną

