








An L-shaped metal bracket is shown inside a circle. To its right is a power drill with a diagonal line through it, indicating it should not be used.	A warning triangle containing an exclamation mark.	A clock face showing approximately 12:30.
A rectangular block is shown on a mat with a hatched pattern. To its right is a similar block with a diagonal line through it, indicating it should not be used.	A warning triangle containing an exclamation mark.	A simple line drawing of a person.

30'







2





1





2





3



4



5



6

